



City of West Covina
Historic Resource Inventory Update

Attachment 2

HRI Update, DPR forms, Individual properties identified in in 2006 survey as eligible
for listing on a local register

*Resource Name or #: 153 N. Willow Ave.

P2 Location: 153 N. Willow Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Southeast elevation, view facing northwest/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 4/9/2019

*Resource Name or #: 206 N. Orange Ave.

P2 Location: 206 N. Orange Ave.

B10 Significance:

The residence on the property appears to have been substantially altered. Alterations include: resizing original window openings, the replacement of original windows, incompatible changes to front entrance, and re-cladding with an incompatible material. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo West elevation, view facing northeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

***Resource Name or #:** 264 N. Willow Ave.

P2 Location: 264 N. Willow Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northwest elevation, view facing southeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

***Resource Name or #:** 306 N. Willow Ave.

P2 Location: 306 N. Willow Ave.

B10 Significance:

The property was evaluated as ineligible for listing in the National Register, the California Register, or for local designation in 2006. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northwest elevation, view facing southeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

*Resource Name or #: 310 N. Puente Ave.

P2 Location: 310 N. Puente Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northwest elevation, view facing southeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

***Resource Name or #:** 321 and 327 N. Sunset Ave.

P2 Location: 321 and 327 N. Sunset Ave.

B10 Significance:

The residence at 327 N. Sunset Ave does not appear to have been substantially altered since it was evaluated in the 2006 survey. A second residence not visible from the public right-of-way may be associated with address 321 N. Sunset Avenue. This residence could not be evaluated. However, because the visible residence on the property does not appear substantially altered since the previous survey, no changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo East elevation, view facing southwest/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 7/6/2019

***Resource Name or #:** 328 N. Vincent Ave.

P2 Location: 328 N. Vincent Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo West elevation, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

*Resource Name or #: 428 N. Sunset Ave.

P2 Location: 428 N. Sunset Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo West elevation, view facing east/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 7/6/2019

*Resource Name or #: 434 N. Orange Ave.

P2 Location: 434 N. Orange Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo West elevation, view facing east/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

Page 1 of 1

Continuation

Update

***Resource Name or #:** 501 N. Vincent Ave.

P2 Location: 501 N. Vincent Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing southwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 507 N. Sunset Ave.

P2 Location: 507 N. Sunset Ave.

B10 Significance:

The residence on the property appears to have been substantially altered since it was evaluated in the 2006 survey. Alterations include: replacement of original windows with vinyl sash and incompatible changes to front entrance. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo East elevation, view facing southwest/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 7/6/2019

***Resource Name or #:** 555 E. Vine Ave.

P2 Location: 555 E. Vine Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing northwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

***Resource Name or #:** 604 E. Barbara Ave.

P2 Location: 604 E. Barbara Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing southwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

*Resource Name or #: 644 N. Hartley Ave.

P2 Location: 644 N. Hartley Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo West elevation, view facing east/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 707 S. Lark Ellen Ave.

P2 Location: 707 S. Lark Ellen Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. The status code assigned in 2006 was 7N1 with the condition that the residence would be eligible for the National Register and California Register if it was restored; however, the restoration work was not specified in 2006. In 2018, the property did not appear to be substantially different from its previous appearance. The proposed status code for this update is 7N.

P5b Description/Date of Photo East elevation, view facing northwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 12/10/2018

***Resource Name or #:** 727 N. Orange Ave.

P2 Location: 727 N. Orange Ave.

B10 Significance:

The property is not visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo East elevation, view facing west/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 7/6/2019

***Resource Name or #:** 841 E. Vine Ave.

P2 Location: 841 E. Vine Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. The status code assigned in 2006 was 7N1 with the condition that the residence would be eligible for the National Register and California Register if it was restored; however, the restoration work was not specified in 2006. In 2018, the property did not appear to be substantially different from its previous appearance. The proposed status code for this update is 7N.

P5b Description/Date of Photo South elevation, view facing northeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

***Resource Name or #:** 856 S. Sunset Ave.

P2 Location: 856 S. Sunset Ave.

B10 Significance:

The property is not fully visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo Northwest elevation, view facing south/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

***Resource Name or #:** 914 S. Lark Ellen Ave.

P2 Location: 914 S. Lark Ellen Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo West elevation, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 12/10/2018

***Resource Name or #:** 943 North Orange Avenue

P2 Location: 943 North Orange Avenue

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo East elevation, view facing southwest/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 4/9/2019

*Resource Name or #: 944 East Cameron Avenue

P2 Location: 944 East Cameron Avenue

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. Original windows have been replaced, but the sizing has not been altered. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo East elevation, view facing southwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 12/10/2018

***Resource Name or #:** 944 E. Vine Ave.

P2 Location: 944 E. Vine Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. Alterations include a rear addition separate from the historic residence. Decorative features including shutters have been removed, but these features may not have been original to the residence. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing south/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 12/10/2018

***Resource Name or #:** 941 W. Merced Ave.

P2 Location: 941 W. Merced Ave.

B10 Significance:

The residence on the property appears to have been substantially altered since it was evaluated in the 2006 survey. Alterations include: resizing original window openings, the replacement of original windows, and incompatible changes to front entrance. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo Southwest elevation, view facing northeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

***Resource Name or #:** 1006 W. Merced Ave.

P2 Location: 1006 W. Merced Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Southeast elevation, view facing west/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

*Resource Name or #: 1006 S. Lark Ellen Ave.

P2 Location: 1006 S. Lark Ellen Ave. (707)

B10 Significance:

The evaluation in 2006 noted that the property had been substantially altered; however, no substantial alterations were observed 2018. The property appears to retain sufficient integrity comparable to other West Covina properties determined eligible for listing in the National Register, the California Register, or for local designation as part of the survey in 2006. The proposed status code of 3S/3CS/5S3 mirrors evaluations of similarly intact properties evaluated in 2006.

P5b Description/Date of Photo West elevation, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 12/10/2018

*Resource Name or #: 1049 S. Willow Ave.

P2 Location: 1049 S. Willow Ave.

B10 Significance:

The residence on the property appears to have been substantially altered. Alterations include: resizing original window openings, the replacement of original windows, incompatible changes to front entrance, and re-cladding with an incompatible material. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo Southeast elevation, view facing northwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

*Resource Name or #: 1051 West Puente Avenue

P2 Location: 1051 West Puente Avenue

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing northwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 1123 West Puente Avenue

P2 Location: 1123 West Puente Avenue

B10 Significance:

The property is not visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo Property not visible from public right-of-way, view facing north/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

*Resource Name or #: 1132 West Merced Avenue

P2 Location: 1132 West Merced Avenue

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northeast elevation, view facing southwest/2019



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 4/9/2019

*Resource Name or #: 1146 W. Puente Ave.

P2 Location: 1146 W. Puente Ave.

B10 Significance:

The evaluation in 2006 noted that the property was not eligible because it had been moved from its original location. While the property may not be eligible for the National Register because it does not meet Criteria Consideration B for moved properties, the property appears to retain sufficient integrity comparable to other West Covina properties determined eligible for listing in the California Register and for local designation in 2006. The recommended status code change reflects this eligibility.

P5b Description/Date of Photo North elevation, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 1154 West Puente Avenue

P2 Location: 1154 West Puente Avenue

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing south/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 1211 W. Workman Ave.

P2 Location: 1211 W. Workman Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing north/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/18/2019

***Resource Name or #:** 1212 E. Puente Ave.

P2 Location: 1212 E. Puente Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 1233 East Idahome Street

P2 Location: 1233 East Idahome Street

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing north/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

*Resource Name or #: 1300 S. Sunkist Ave.

P2 Location: 1300 S. Sunkist Ave.

B10 Significance:

The residence on the property appears to have been substantially altered since it was evaluated in the 2006 survey. Alterations include: resizing original window openings, the replacement of original windows, and re-cladding with an incompatible material. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo Northwest elevation, view facing southeast/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/18/2019

***Resource Name or #:** 1307 S. Willow Ave.

P2 Location: 1307 S. Willow Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Southeast elevation, view facing northwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 1327 S. California Ave.

P2 Location: 1327 S. California Ave.

B10 Significance:

The residence on the property appears to have been substantially altered since it was evaluated in the 2006 survey. Alterations include: incompatible changes to front entrance, re-cladding with an incompatible material, and roofline reconfigurations. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo Southeast elevation, view facing northwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

***Resource Name or #:** 1358 E. Workman Ave.

P2 Location: 1358 E. Workman Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing southwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

*Resource Name or #: 1449 E. Puente Ave.

P2 Location: 1449 E. Puente Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. Original windows have been replaced with vinyl sash, but the sizing has not been altered. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing northwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

Page 1 of 1

Continuation

Update

***Resource Name or #:** 1518 E. Rowland Ave.

P2 Location: 1518 E. Rowland Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing southwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

*Resource Name or #: 1720 S. Willow Ave

P2 Location: 1720 S. Willow Ave

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northwest elevation, view facing south/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 1902 E. Rowland Ave.

P2 Location: 1902 E. Rowland Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo North elevation, view facing southwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/11/2019

***Resource Name or #:** 2141 E Cameron Ave

P2 Location: 2141 E Cameron Ave

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing northwest/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 2219 W. Mossberg Ave.

P2 Location: 2219 W. Mossberg Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Southwest elevation, view facing east/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 2223 W. Mossberg Ave.

P2 Location: 2223 W. Mossberg Ave.

B10 Significance:

The residence on the property appears to have been substantially altered since it was evaluated in the 2006 survey. Alterations include: resizing original window openings and the replacement of original windows with vinyl sash. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo South elevation, view facing north/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

*Resource Name or #: 2225 W. Merced Ave.

P2 Location: 2225 W. Merced Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. Original windows have been replaced with vinyl sash, but the sizing has not been altered. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Southwest elevation, view facing east/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

***Resource Name or #:** 2314 W. Clydewood Ave.

P2 Location: 2314 W. Clydewood Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northeast elevation, view facing west/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

*Resource Name or #: 2322 E. Cortez Ave.

P2 Location: 2322 E. Cortez Ave.

B10 Significance:

The residence on the property appears to have been substantially altered since it was evaluated in the 2006 survey. Though the property was not fully visible from the public right-of-way, alterations appear to include: resizing original window openings, the replacement of original windows, and re-cladding with an incompatible material. The property does not retain sufficient integrity to be eligible for listing in the National Register, the California Register, or for local designation.

P5b Description/Date of Photo Property not visible from public right-of-way, view facing south/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

Page 1 of 1

Continuation

Update

***Resource Name or #:** 2328 W Pacific Ave

P2 Location: 2328 W Pacific Ave

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Northeast elevation, view facing southwest/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

*Resource Name or #: 2339 W. Francisquito Ave.

P2 Location: 2339 W. Francisquito Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo Southwest elevation, view facing east/2019



Recorded By Elysha Paluszek
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 6/5/2019

***Resource Name or #:** 2527 E. Cameron Ave.

P2 Location: 2527 E. Cameron Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing north/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 2750 E. Cortez Ave.

P2 Location: 2750 E. Cortez Ave.

B10 Significance:

The property is not visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo Property not visible from public right-of-way, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

*Resource Name or #: 2828 E. Cortez Ave

P2 Location: 2828 E. Cortez Ave

B10 Significance:

The property is not visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo Property not visible from public right-of-way, view facing southeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 3121 E. Cameron Ave.

P2 Location: 3121 E. Cameron Ave.

B10 Significance:

The property is not visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo South elevation, view facing northeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 3129 E. Virginia Ave.

P2 Location: 3129 E. Virginia Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing northeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

***Resource Name or #:** 3311 E. Cameron Ave.

P2 Location: 3311 E. Cameron Ave.

B10 Significance:

The property is not visible from the public right-of-way. Further evaluation is needed to determine if it remains eligible for listing in the National Register, the California Register, and for local designation.

P5b Description/Date of Photo Property not visible from public right-of-way, view facing north/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018

*Resource Name or #: 3535 E. Cortez Ave.

P2 Location: 3535 E. Cortez Ave.

B10 Significance:

The property does not appear to have been substantially altered since it was evaluated in the 2006 survey. No changes are proposed to the status code assigned in 2006.

P5b Description/Date of Photo South elevation, view facing northeast/2018



Recorded By Allison Lyons
GPA Consulting
617 S. Olive Street, Suite 910
Los Angeles, CA 90014

Date Recorded: 11/28/2018